

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**


【図1】



【図2】



【図 3】



【図4】




Figure 1 consists of three views of a magnetic head assembly:

- (a) Top view: Shows a central slider 902 with a coil 920G on top. The assembly is supported by a base 902. Various components are labeled with reference numerals: 938, 964, 920R, 926R, 926B, 942, 920G, 926G, 500, 918B, 952B, 952R, 918R, 930, 950, 950A, 950B, 954, 960, 962, 964, 966, 968, 970, 972, 974, 976, 978, 980, 982, 984, 986, 988, 990, 992, 994, 996, 998, 1000.
- (b) Side cross-sectional view: Shows the assembly mounted on a substrate 3. The slider 902 is shown in cross-section, with the coil 920G and magnetic head 926G. The assembly is supported by a base 902. Various components are labeled with reference numerals: 938, 964, 920R, 926R, 926B, 942, 920G, 926G, 500, 918B, 952B, 952R, 918R, 930, 950, 950A, 950B, 954, 960, 962, 964, 966, 968, 970, 972, 974, 976, 978, 980, 982, 984, 986, 988, 990, 992, 994, 996, 998, 1000.
- (c) Bottom view: Shows the slider 902 from below, with four mounting holes 950A. The slider is supported by a base 902. Various components are labeled with reference numerals: 938, 964, 920R, 926R, 926B, 942, 920G, 926G, 500, 918B, 952B, 952R, 918R, 930, 950, 950A, 950B, 954, 960, 962, 964, 966, 968, 970, 972, 974, 976, 978, 980, 982, 984, 986, 988, 990, 992, 994, 996, 998, 1000.

【図 6】

